



Private Client

DEKRA Boksburg  
Bentel Ave - 1459  
BOKSBURG - GT  
011 826 4386



**Assignment**

Client	Private Client	Inspection Location	DEKRA Boksburg
Requested Date	09/04/2026		573 TRICHARDT ROAD - 1459
Inspection Date	09/04/2026		BOKSBURG DEKRA - GT

**Vehicle Data**

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK CBK MOTORS
Manufacturer	AUDI	Registration Number	KHK403NW
Model	A5	Register Number	DNW839K
VIN	WUAZZZ8T7BA902340	Date Of First Licensing	
Engine Number		Last COR	2026/03/19
Doors	2	License Expiry Date	
Color	SILVER	Power / Displacement	331kW/4163cc
Year Model	2011	Paint Finish	M - METALLIC
Km Reading	68,644 KM	Fuel	PETROL
Cab / Body Type	COUPE	Transmission	AUTOMATIC

**Vehicle Options & Accessories**

**Items**

6 airbags; 2x electrical windows; 4x4; ABS; Airconditioning; Airconditioning auto.; Alarm system; Alloy Wheels; Car phone preparation; Central locking; Cruise control; Driver's seat elec.; El. mirrors; ESP (el. stability progr.); Fog lights; Headlamp washer; Leather interior; Leather steering wheel; Multifunction steering wheel; Navigation system; On-board computer; Park sensor; Power steering; Radio cd; Sun roof; Traction control system; Xenon headlights;


**VEHICLE INSPECTION**



**Damage**

**Repair Way**

Windscreen Chipped



**Brakes**

**Brake Test Results**

Brake efficiency tested during road test.

	Left	Right	Axle Weight [KG]	Deceleration [m/s <sup>2</sup> ]
	Braking Force [KN]	Braking Force [KN]		
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

**Tyres and Rims**

**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/35/19	96Y	Dunlop	SP Sport Max	V	1725	5 mm
Front Right	255/35/19	96Y	Dunlop	SP Sport Max	V	1725	5 mm
Rear Left	255/35/19	96Y	Dunlop	SP Sport Max	V	1725	5 mm
Rear Right	255/35/19	96Y	Dunlop	SP Sport Max	V	1725	5 mm

\* Tyre Legend: V=Virgin, R=Recap



### Diagnostic

A vehicle diagnostic has not been conducted.

### Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: in accordance with the age and mileage of the vehicle minor wear and tear to be expected on the interior of the vehicle.  
Body • Exterior: In accordance to the age and mileage of the vehicle minor dents and scratches visible on some body panels. Windscreen chipped to be stopped.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

David Olwagen

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Expansion Bottle



Chassis2



No Spare wheel



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD




RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



DOCUMENT




ENGINE 1



CHASSIS



ENGINE 2



ADDITIONAL 10



Windscreen