



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	13/07/2026		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	13/07/2026		BOKSBURG - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS CBK MOTORS
Manufacturer	BMW	Registration Number	HZ56KFGP
Model	X3 M40D SAV (SPORT) AWD DSL 8-SP STEPTRONIC [2019-2022]	Register Number	ZXP357W
VIN	WBATX96040NA62976	Date Of First Licensing	
Engine Number		Last COR	04/04/2025
Doors	5	License Expiry Date	31/05/2027
Color	BLACK	Power / Displacement	240kW/2993cc
Year Model	2019	Paint Finish	M - METALLIC
Km Reading	87,445 KM	Fuel	DIESEL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items


(Fixed) tow bar; 8 airbags; 4x electrical windows; 4x4; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; Car phone preparation; CD changer; Central locking; Cruise control; Driver's seat elec.; Driver's seat with memory; El. fold-away mirrors; ESP (el. stability progr.); Fog lights; Front armrest; Handsfree car kit; Leather interior; Leather steering wheel; Multifunction steering wheel; Navigation system; On-board computer; Park sensor; Power steering; Rain sensor; Seat heating; Sliding roof el.;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

Brake efficiency tested during road test.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/45R20	103W	BRIDGESTONE	ALENZA	V	1825	5 mm
Front Right	245/45R20	103W	BRIDGESTONE	ALENZA	V	1625	5 mm
Rear Left	275/40R20	106W	BRIDGESTONE	ALENZA	V	1524	5 mm
Rear Right	275/40R20	106W	BRIDGESTONE	ALENZA	V	1424	5 mm
Spare	T135/80R18	104M	MAXXIS	SPARE TIRE	V	3817	5 mm

* Tyre Legend: V=Virgin, R=Recap



Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents, scratches and stone chips on some body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE


Technician

Ofentse Morankwane

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


TEST SHEET



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LR TYRE TREAD



LF TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD




LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



CAHSSIS2



AWD



COOLANT BOTTLE



SPAREWHEEL



OIL CAP NO DIPSTICK