




Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	06/07/2026		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	06/07/2026		BOKSBURG - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS CBK MOTORS
Manufacturer	MERCEDES-BENZ	Registration Number	LJ20BZGP
Model	C 200	Register Number	FLP003X
VIN	W1K2060422R112565	Date Of First Licensing	
Engine Number	254915V04064	Last COR	06/07/2026
Doors	5	License Expiry Date	31/01/2027
Color	WHITE	Power / Displacement	150KW/1496CCM
Year Model	2023	Paint Finish	C - COMMON
Km Reading	68,826 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items


8 airbags; 4x electrical windows; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; Central locking; Cruise control; Driver's seat elec.; El. fold-away mirrors; El. mirrors; ESP (el. stability progr.); Fog lights; Front armrest; Handsfree car kit; Leather interior; Leather steering wheel; Multifunction steering wheel; Navigation system; On-board computer; Park sensor; Power steering; Radio / Cassette; Rain sensor; Sun roof; Traction control system; Xenon headlights;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	4.1	3.4	-	
Rear	3.2	2.7	-	
Emergency / Parking	2.1	1.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/45R18	95Y	Bridgestone	Potenza	V	0125	5 mm
Front Right	225/45R28	95Y	Bridgestone	Potenza	V	0225	5 mm
Rear Left	245/40R18	97Y	Bridgestone	Potenza	V	3924	4 mm
Rear Right	245/40R18	97Y	Bridgestone	Potenza	V	3924	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient



Comments

General Comments: ACCORDING TO THE AGE AND MILAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR AND INTERIOR ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents stone chips and or scratches on various body panels.

Tyres and Rims: No spare wheel

Undercarriage: Undercarriage and engine mostly covered.

Options & Accessories

TINTED WINDOWS, CENTRE BRAKE LIGHT,

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE






Technician




Bianca Gleave


This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.







Oil cap




Expansion bottle




covered



Covered



Chassis 2




No spare wheel



LR TYRE TREAD




LF TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD



Brake report



Test report