



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	10/07/2025		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	10/07/2025		johannesburg - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	CBK MOTORS
Manufacturer	TOYOTA	Registration Number	HHN966L
Model	HILUX 2.4 GD S A/C DSL PU [2019-2021]	Register Number	HMC619L
VIN	AHTEB8CB502805110	Date Of First Licensing	
Engine Number	2GDC561498	Last COR	10/07/2025
Doors	2	License Expiry Date	30/11/2025
Color	WHITE	Power / Displacement	110kw 2393ccm
Year Model	2019	Paint Finish	C - COMMON
Km Reading	66,706 KM	Fuel	DIESEL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

2 airbags; 2x electrical windows; ABS; Airconditioning; Alarm system; Central locking; El. mirrors; Power steering; Radio cd;



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.3	2.7	-	
Rear	2.0	1.9	-	
Emergency / Parking	1.7	1.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/70R15C	106/104S	Continental	Worldcontact	V	2721	4 mm
Front Right	205/70R16 C	106/104S	Continental	Worldcontact	V	0421	4 mm
Rear Left	205/70R15C	106/104S	Continental	Worldcontact	V	2521	4 mm
Rear Right	205/70R16C	106/104S	Continental	Worldcontact	V	2721	3 mm
Spare	205/70R15C	106/104S	Continental	Worldcontact	V	0000	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Cosmetical spray work done to some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Tumelo Molekoa

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE REAR




90 DEGREE FRONT




90 DEGREE RIGHT



90 DEGREE LEFT



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Expansion bottle



Oil cap and dipstick



Chassis 2



Sparewheel




CHASSIS



ENGINE 2




ENGINE 1




VIN PLATE OR STICKER



LICENSE DISC



BRAKE TEST REPORT



ROADWORTHY TEST SHEET