



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	20/10/2025		573 Trichard Road - 1459
Inspection Date	20/10/2025		Boksburg - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS
Manufacturer	LAND ROVER	Registration Number	DY41JNGP
Model	DISCOVERY SPORT 2.2 SD4 HSE DSL 4X4 AT [2015-2018]	Register Number	WMB341W
VIN	SALCA2AD6GH554137	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	GREY	Power / Displacement	
Year Model	2015	Paint Finish	M - METALLIC
Km Reading	110,687 KM	Fuel	DIESEL
Cab / Body Type	SUV	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

2 airbags; 10 airbags; 4x electrical windows; ABS; Alarm system; Alloy Wheels; Central locking; Cruise control; Driver's seat elec.; El. fold-away mirrors; ESP (el. stability progr.); Fog lights; Handsfree car kit; Headlamp washer; Leather interior; Leather steering wheel; Multifunction steering wheel; Navigation system; Park sensor; Power steering; Sun roof; Traction control system; Xenon headlights;



Brakes

Brake Test Results

Brake efficiency tested during road test.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/45R20	103W	Continental	Crosscontact	V	2423	2 mm
Front Right	245/45R20	103W	Continental	Crosscontact	V	0923	3 mm
Rear Left	245/45R20	103W	Continental	Crosscontact	V	1322	5 mm
Rear Right	245/45R20	103W	Continental	Crosscontact	V	0223	5 mm
Spare	T155/85R18	115M	Continental	CST17	V	0000	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Rain at time of inspection

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ON EXTERIOR, INTERIOR AND MECHANICAL PARTS.Engine Compartment: Engine and transmission mostly covered underneath.

Body • Exterior: Minor dents, scratches and stone chips on some body panels.Cosmetical spraywork done to some body panels.

Tyres and Rims: Left front tyre slight sidewall damage.

Road Test: 4x4 Function not tested

Options & Accessories

RADIO USB, REARVIEW CAMERA

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Tumelo Molekoa

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Expansion bottle




Oil cap and dipstick



Chassis 2



Sparewheel



Roadworthy test sheet



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



CHASSIS



ENGINE 2