CONDITION REPORT

Report No:
2017322219
DATE
06/11/2026

Private Client
,

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386







Assignment

Client	**Private Client**	Inspection Location	**BOKSBURG DEKRA** **316 Bental Ave - 1459** **Boksburg - GT**
Requested Date	**06/11/2026**		
Inspection Date	**06/11/2026**		

Vehicle Data

Vehicle Type	**LIGHT LOAD VEHICLE**	Registered Owner	**CBK MOTORS CBK MOTORS**
Manufacturer	**MAZDA**	Registration Number	**KJY295NW**
Model	**BT-50 3.2 MZ-CD SLE FREESTYLE CAB DSL PU [2012-2014]**	Register Number	**RPY287W**
		Date Of First Licensing	
VIN	**AFBGXXMJ2GCE57841**	Last COR	**06/11/2026**
Engine Number	**SA2KGCE57841**	License Expiry Date	**30/09/2026**
Doors	**4**	Power / Displacement	**147Kw. 3198Ccm**
Color	**WHITE**	Paint Finish	**C - COMMON**
Year Model	**2012**	Fuel	**DIESEL**
Km Reading	**277,592 KM**	Transmission	**MANUAL**
Cab / Body Type	**SUPER CAB**		

Vehicle Options & Accessories

Items

(Fixed) tow bar; 2 airbags; 2x electrical windows; ABS; Airconditioning; Alarm system; Alloy Wheels; Car phone preparation; Central locking; Cruise control; El. mirrors; ESP (el. stability progr.); Fog lights; Front armrest; Leather steering wheel; Multifunction steering wheel; On-board computer; Power steering; Radio cd; Traction control system;


VEHICLE INSPECTION

DEKRA

CONDITION REPORT

Report No: 2017322219
DATE 06/11/2026

Damage	Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s^2]
Front	4.1	3.2	-	
Rear	3.8	3.3	-	
Emergency / Parking	2.9	2.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R17	112T	Velocity	Raptor	V	0120	6 mm
Front Right	265/65R17	112T	Velocity	Raptor	V	0320	6 mm
Rear Left	265/65R17	112T	Velocity	Raptor	V	0320	4 mm
Rear Right	265/65R17	112T	Velocity	Raptor	V	0220	4 mm
Spare	265/65R17	112H	Goodyear	Wrangler	V	1612	8 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFBGXXMJ2GCE57841

CONDITION REPORT

Report No:
2017322219
DATE
06/11/2026

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents scratches and stone chips

Options & Accessories

SIDE STEPS CATTLE RAIL MUDFLAPS WIND DETECTORS BONNET SHIELD SPOT BAR REAR SLIDING WINDOW CATTLE RAIL COVER LOADING BIN RUBBERIZED

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

IAN WHITTAKER

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFBGXXMJ2GCE57841


DEKRA

CONDITION REPORT

Report No:
2017322219
DATE
06/11/2026



Brake report



Test sheet



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFBGXXMJ2GCE57841

DEKRA


CONDITION REPORT

Report No:
2017322219
DATE
06/11/2026




ODOMETER


90 DEGREE FRONT


90 DEGREE RIGHT


90 DEGREE REAR


90 DEGREE LEFT


LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFBGXXMJ2GCE57841

DEKRA

CONDITION REPORT

Report No:
2017322219
DATE
06/11/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare tyre



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


DEKRA

CONDITION REPORT


Report No:
2017322219
DATE
06/11/2026



ENGINE 1



ENGINE 2



CHASSIS



Chassis 2



Oil cap and dipstick



Air-conditioning

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFBGXXMJ2GCE57841

DEKRA

CONDITION REPORT


Report No:
2017322219
DATE
06/11/2026



Coolant level



Triangle



Door Front Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFBGXXMJ2GCE57841