
CONDITION REPORT

Report No:
2017318976
DATE
29/10/2026

Private Client
,

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386




Assignment

Client	**Private Client**	Inspection Location	**BOKSBURG DEKRA** **316 Bental Ave - 1459** **DEKRA Boksburg - GT**
Requested Date	**29/10/2026**		
Inspection Date	**29/10/2026**		

Vehicle Data

Vehicle Type	**PASSENGER VEHICLE**	Registered Owner	**CBK MOTORS**
Manufacturer	**MERCEDES BENZ**	Registration Number	**BL16HCZN**
Model	**C180**	Register Number	**VJJ552W**
VIN	**WDD2050402R024816**	Date Of First Licensing	
Engine Number		Last COR	**29/10/2026**
Doors	**4**	License Expiry Date	**31/07/2027**
Color	**GREY**	Power / Displacement	**115kw**
Year Model	**2014**	Paint Finish	**M - METALLIC**
Km Reading	**139,389 KM**	Fuel	**PETROL**
Cab / Body Type	**SEDAN**	Transmission	**AUTOMATIC**

Vehicle Options & Accessories


Items

8 airbags; 4x electrical windows; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; Central locking; El. fold-away mirrors; ESP (el. stability progr.); Handsfree car kit; Leather interior; Leather steering wheel; Multifunction steering wheel; Park sensor; Power steering; Radio cd; Rain sensor; Sliding roof el.; Traction control system; Xenon headlights;

VEHICLE INSPECTION

CONDITION REPORT

Report No:
2017318976
DATE
29/10/2026



Damage	Repair Way
Rim Front Right Chipped	

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s^2]
Front	2.6	2.1	-	
Rear	3.5	2.5	-	
Emergency / Parking	3.8	2.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40R18	92W	Dunlop	SP Sport	V	3824	4 mm
Front Right	225/45R18	95Y	Bridgestone	Potenza	V	4822	2 mm
Rear Left	255/40R18	95Y	Goodyear	Eagle	V	5023	5 mm
Rear Right	255/40R18	95Y	Goodyear	Eagle	V	5023	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Inspection conditions for the vehicle inspection were sufficient

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R024816

CONDITION REPORT

Report No:
2017318976
DATE
29/10/2026

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Engine, transmission and undercarriage mostly covered underneath.
Electrical Components and Instruments: Auxiliary battery malfunction warning illuminated at time of inspection.
Body • Exterior: Minor dents,scratches and stone chips on some body panels.Cosmetical enhancements done to some body panels.
Brakes: Brake discs slightly dished.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Tumelo Molekoa

This document was created electronically and is valid without signature.


General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R024816

CONDITION REPORT

Report No:
2017318976
DATE
29/10/2026



Test sheet



Auxiliary battery malfunction



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R024816

DEKRA

CONDITION REPORT


Report No:
2017318976
DATE
29/10/2026




90 DEGREE FRONT



90 DEGREE LEFT




REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE RIGHT



Oil cap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R024816

DEKRA

CONDITION REPORT

Report No:
2017318976
DATE
29/10/2026




Coolant bottle



ENGINE 1



CHASSIS



ENGINE 2



Chassis 2



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R024816

DEKRA

CONDITION REPORT

Report No:
2017318976
DATE
29/10/2026




LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Brake test report



No sparewheel



Warning triangle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R024816

CONDITION REPORT

Report No:
2017318976
DATE
29/10/2026



LICENSE DISC



VIN PLATE OR STICKER



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2050402R024816