CONDITION REPORT

Report No:
2017322297
DATE
06/11/2026

Private Client
,

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386







Assignment

Client	**Private Client**	Inspection Location	**BOKSBURG DEKRA** **316 BENTELL AVE BOKSBURG - 1459** **BOKSBURG - GT**
Requested Date	**06/11/2026**		
Inspection Date	**06/11/2026**		

Vehicle Data

Vehicle Type	**PASSENGER VEHICLE**	Registered Owner	**CBK MOTORS (PTY) LTD**
Manufacturer	**VOLKSWAGEN**	Registration Number	**JV41GPGP**
Model	**POLO 1.0 TSI HIGHLINE 85KW 5-DR DSG [2018-2019]**	Register Number	**HGM707K**
		Date Of First Licensing	
VIN	**AAVZZZAWZJU005676**	Last COR	
Engine Number	**DKJ002761**	License Expiry Date	**30/04/2027**
Doors	**4**	Power / Displacement	**85kw 999ccm**
Color	**WHITE**	Paint Finish	**C - COMMON**
Year Model	**2018**	Fuel	**PETROL**
Km Reading	**103,533 KM**	Transmission	**AUTOMATIC**
Cab / Body Type	**HATCHBACK**		

Vehicle Options & Accessories

Items

6 airbags; 4x electrical windows; ABS; Airconditioning; Alarm system; Alloy Wheels; Central locking; Cruise control; El. mirrors; Fog lights; Handsfree car kit; Leather steering wheel; Multifunction steering wheel; Park sensor; Power steering; Radio / Cassette; Rain sensor;


VEHICLE INSPECTION

DEKRA

CONDITION REPORT

Report No:
2017322297
DATE
06/11/2026

Damage **Repair Way**



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.0	2.9	-	
Rear	2.1	2.0	-	
Emergency / Parking	1.7	1.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55R16	91V	Continental	Contact 5	V	4523	5 mm
Front Right	195/55R16	87V	Continental	Contact 5	V	0825	5 mm
Rear Left	195/55R16	91V	Continental	Contact 5	V	4023	5 mm
Rear Right	195/55R16	91V	Continental	Contact 5	V	4523	5 mm
Spare	185/65R15	88H	Rapid	P309	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Inspection conditions for the vehicle inspection were sufficient

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU005676

CONDITION REPORT

Report No:
2017322297
DATE
06/11/2026

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Minor dents,scratches and stone chips on some body panels.
Undercarriage: Engine, transmission and undercarriage mostly covered underneath.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Tumelo Molekoa

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU005676


DEKRA

CONDITION REPORT

Report No:
2017322297
DATE
06/11/2026


Brake Test Report
DEKRA BOKSBURG
316 BENTAL AVE
PASSED

Brake test report



Roadworthy test sheet



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU005676


DEKRA

CONDITION REPORT

Report No:
2017322297
DATE
06/11/2026




ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU005676

DEKRA

CONDITION REPORT

Report No:
2017322297
DATE
06/11/2026



LR TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017322297
DATE
06/11/2026



ENGINE 1



ENGINE 2



CHASSIS



Chassis 2



Coolant bottle



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU005676

DEKRA

CONDITION REPORT

Report No:
2017322297
DATE
06/11/2026



Warning triangle



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZJU005676