



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	08/04/2026		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	08/04/2026		BOKSBURG - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS CBK MOTORS
Manufacturer	BMW	Registration Number	CFV746MP
Model	3 SERIES	Register Number	STM817A
VIN	ABMCA98080AH08302	Date Of First Licensing	
Engine Number		Last COR	2017/04/09
Doors	4	License Expiry Date	
Color	WHITE	Power / Displacement	85Kw/1796Cc
Year Model	1996	Paint Finish	C - COMMON
Km Reading	94,185 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items


2 airbags; 4x electrical windows; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; Car phone preparation; Central locking; El. mirrors; ESP (el. stability progr.); Fog lights; Leather steering wheel; On-board computer; Power steering; Radio cd; Xenon headlights;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.1	2.0	-	
Rear	1.9	1.8	-	
Emergency / Parking	2.3	1.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/65R15	91T	General	Altimax	V	3722	4 mm
Front Right	195/65R15	91T	General	Altimax	V	3722	4 mm
Rear Left	195/65R15	91T	General	Altimax	V	3722	4 mm
Rear Right	195/65R15	91T	General	Altimax	V	3722	4 mm
Spare	195/65R15	91T	Road stone	Eurovis	V	0820	4 mm

* Tyre Legend: V=Virgin, R=Recap



Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents stone chips and or scratches on various body panels. Cosmetical spray work on various body panels.

Options & Accessories

TINTED WINDOWS, CENTRE BRAKE LIGHT,

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Bianca Gleave

This document was created electronically and is valid without signature.


General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Spare wheel




Expansion bottle




Oil cap and dipstick







Chassis 2




Brake report



ADDITIONAL 11







RF TYRE TREAD




LICENSE DISC




VIN PLATE OR STICKER



ENGINE 1



CHASSIS



ENGINE 2