



CONDITION REPORT



Report No:
2017296758
DATE
10/09/2026

Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	10/09/2026		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	10/09/2026		BOKSBURG - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS CBK MOTORS
Manufacturer	BMW	Registration Number	LP28KFGP
Model	M5 8-SP AT [2013-2017]	Register Number	SYJ374W
VIN	WBSFV92050DX96713	Date Of First Licensing	
Engine Number	20450542	Last COR	10/09/2026
Doors	4	License Expiry Date	30/11/2026
Color	WHITE	Power / Displacement	412Kw. 4395Ccm
Year Model	2013	Paint Finish	C - COMMON
Km Reading	110,568 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

8 airbags; 4x electrical windows; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; Car phone preparation; Central locking; Cruise control; Driver's seat elec.; El. fold-away mirrors; ESP (el. stability progr.); Fog lights; Front armrest; Handsfree car kit; Headlamp washer; Leather interior; Leather steering wheel; Multifunction steering wheel; Navigation system; On-board computer; Park sensor; Power steering; Radio cd; Rain sensor; Seat heating; Sliding roof el.; Sun roof; Traction control system; Xenon headlights;

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBSFV92050DX96713



CONDITION REPORT



Report No:
2017296758
DATE
10/09/2026

Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.3	2.6	-	
Rear	3.1	2.3	-	
Emergency / Parking	2.7	2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/35ZR20	99Y	Michelin	Pilot	V	0823	3 mm
Front Right	265/35ZR20	99Y	Michelin	Pilot	V	3420	1 mm
Rear Left	295/30ZR20	101Y	Michelin	Pilot	V	5020	0 mm
Rear Right	295/30ZR20	101Y	Michelin	Pilot	V	5020	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBSFV92050DX96713

**CONDITION REPORT**

Report No:
2017296758
DATE
10/09/2026

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents scratches and stone chips. Cosmetic spray work various panels
Tyres and Rims: Rear tyres scuffed and right front tyre on 1mm to be replaced soon
Undercarriage: Undercarriage mostly covered

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

IAN WHITTAKER

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBSFV92050DX96713



CONDITION REPORT




Report No:


2017296758

DATE

10/09/2026



Brake report



Test sheet




FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBSFV92050DX96713



CONDITION REPORT



Report No:
2017296758
DATE
10/09/2026



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBSFV92050DX96713




CONDITION REPORT




Report No:
2017296758
DATE
10/09/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No spare tyre



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBSFV92050DX96713



CONDITION REPORT



Report No:
2017296758
DATE
10/09/2026



ENGINE 1



ENGINE 2



CHASSIS



REAR



Oil cap



Air-conditioning

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBSFV92050DX96713



CONDITION REPORT



Report No:
2017296758
DATE
10/09/2026



Expansion bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBSFV92050DX96713