



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	08/09/2026		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	08/09/2026		BOKSBURG - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK CBK MOTORS
Manufacturer	CHEVROLET	Registration Number	CJ81TGGP
Model	SPARK 1.2 LS 5-DR [2013-2014]	Register Number	FFP402K
VIN	ADMMF48DLC4610877	Date Of First Licensing	
Engine Number	B12D1771146KC3	Last COR	
Doors	5	License Expiry Date	30/06/2027
Color	BLACK	Power / Displacement	
Year Model	2013	Paint Finish	M - METALLIC
Km Reading	124,547 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items


2 airbags; 2x electrical windows; ABS; Airconditioning; Alloy Wheels; Central locking; ESP (el. stability progr.); Fog lights; Multifunction steering wheel; Power steering; Radio cd;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.3	2.0	-	
Rear	1.8	1.5	-	
Emergency / Parking	1.1	1.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/60R15	81T	TRACMAX	X-PRIVIO	V	0123	5 mm
Front Right	165/60R15	81T	TRACMAX	X-PRIVIO	V	0123	5 mm
Rear Left	165/60R15	81T	TRACMAX	X-PRIVIO	V	0123	5 mm
Rear Right	165/60R15	81T	TRACMAX	X-PRIVIO	V	0123	5 mm
Spare	155/70R14	77T	HANKOOK	OPTIMO	V	0912	6 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Inspection conditions for the vehicle inspection were sufficient



Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks


THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician


Ofentse Morankwane

This document was created electronically and is valid without signature.


General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




BRAKE REPORT




TEST SHEET




FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER




90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD



SPAREWHEEL



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2




CHASSIS



CHASSIS2



COOLANT BOTTLE



OILCAP AND DIPSTICK



ADDITIONAL 50



Chassis



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: ADMMF48DLC4610877