




Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	17/08/2026		316 Bentel Ave - 1459
Inspection Date	17/08/2026		DEKRA Boksburg - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK CBK MOTORS
Manufacturer	VOLKSWAGEN	Registration Number	FF03KKGP
Model	GOLF	Register Number	GSP485K
VIN	WVWZZZAUZGW235323	Date Of First Licensing	
Engine Number		Last COR	2026/08/17
Doors	5	License Expiry Date	
Color	GREY	Power / Displacement	162Kw/1984Cc
Year Model	2016	Paint Finish	M - METALLIC
Km Reading	97,311 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items


6 airbags; 4x electrical windows; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; Central locking; Cruise control; El. mirrors; ESP (el. stability progr.); Fog lights; Front armrest; Handsfree car kit; Headlamp washer; Leather interior; Leather steering wheel; Multifunction steering wheel; On-board computer; Park sensor; Power steering; Radio / Cassette; Seat heating; Sliding roof el.; Sun roof; Traction control system; Xenon headlights;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.6	2.8	-	
Rear	2.6	2.3	-	
Emergency / Parking	2.5	2.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/35R19	88Y	Pirelli	Pzero	V	4123	4 mm
Front Right	225/35R19	88Y	Pirelli	Pzero	V	4123	4 mm
Rear Left	225/35R19	88Y	Pirelli	Pzero	V	4123	4 mm
Rear Right	225/35R19	88Y	Pirelli	Pzero	V	4123	4 mm
Spare	T125/70R18	99M	Continental	Temp	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap



Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents stone chips and or scratches on various body panels.

Axle and Suspension: Both front control arm bushes slightly perished

Undercarriage: Undercarriage mostly covered, limited visibility.

Options & Accessories

TINTED WINDOWS, CENTRE BRAKE LIGHT, ROOF SPOILER.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Bianca Gleave

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Expansion bottle



Oil cap and dipstick



Spare wheel




Ac cluster




Partly covered




Chassis 2




Brake report




Test report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT




90 DEGREE REAR




90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WWZZZAUGW235323