




CONDITION REPORT



Report No:
2017295585
DATE
08/09/2026

Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	08/09/2026		316 Bentel Ave - 1459
Inspection Date	08/09/2026		DEKRA Boksburg - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS
Manufacturer	FORD	Registration Number	DF22CLZN
Model	RANGER 2.2 TDCI XL D-CAB DSL PU [2017-2020]	Register Number	YKB599W
VIN	AFAPXXMJ2PHK26552	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	
Color	SILVER	Power / Displacement	110kw 2200ccm
Year Model	2017	Paint Finish	M - METALLIC
Km Reading	55,857 KM	Fuel	DIESEL
Cab / Body Type	DOUBLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items

2 airbags; 4x electrical windows; ABS; Airconditioning; Alarm system; Alloy Wheels; Central locking; El. mirrors; ESP (el. stability progr.); Handsfree car kit; Multifunction steering wheel; Power steering; Radio / Cassette; Traction control system;

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PHK26552



CONDITION REPORT



Report No:
2017295585
DATE
08/09/2026

Damage

Repair Way



Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	3.0	3.6	-	
Rear	2.4	3.0	-	
Emergency / Parking	2.5	3.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/70R17	112T	Continental	Crosscontact	V	1226	8 mm
Front Right	255/70R17	112T	Continental	Crosscontact	V	2226	8 mm
Rear Left	255/70R17	112T	Continental	Crosscontact	V	2026	8 mm
Rear Right	255/70R17	112T	Continental	Crosscontact	V	1226	8 mm
Spare	265/70R16	111T	Continental	Crosscontact	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PHK26552

**CONDITION REPORT**

Report No:
2017295585
DATE
08/09/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Engine partly covered underneath.
Body • Exterior: Minor dents, scratches and stone chips on some body panels. Cosmetical enhancements done to some body panels
Undercarriage: Undercarriage dirty at time of inspection.

Options & Accessories

SIDESTEPS, TOURNEAU COVER

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Tumelo Molekoa

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PHK26552



CONDITION REPORT



Report No:

2017295585

DATE

08/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PHK26552



CONDITION REPORT



Report No:
2017295585
DATE
08/09/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PHK26552



CONDITION REPORT



Report No:
2017295585
DATE
08/09/2026



RF TYRE TREAD



Sparewheel



Coolant bottle



Oil cap and dipstick



Aircon working



Chassis 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PHK26552



CONDITION REPORT



Report No:
2017295585
DATE
08/09/2026



ENGINE 1



ENGINE 2




CHASSIS



VIN PLATE OR STICKER



LICENSE DISC



BRAKE TEST REPORT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PHK26552



CONDITION REPORT



Report No:
2017295585
DATE
08/09/2026

ROADWORTHY TEST SHEET

Vehicle No: 2017295585

Inspector: [Signature]

Vehicle Details: [Handwritten information]

Inspection Categories: [List of items with checkboxes]

Overall Result: [Handwritten 'PASS']

Inspector's Signature: [Signature]

Vehicle's Signature: [Signature]

ROADWORTHY TEST SHEET

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AFAPXXMJ2PHK26552