



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	19/10/2026		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	19/10/2026		BOKSBURG - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS CBK MOTORS
Manufacturer	BMW	Registration Number	LW59FSGP
Model	X5 XDRIVE30D XLINE DSL SPORT ACTIVITY STEPTRONIC [2018-2024]	Register Number	ZMF924W
VIN	WBACV62090LB14348	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2018	Paint Finish	C - COMMON
Km Reading	100,863 KM	Fuel	DIESEL
Cab / Body Type	SUV	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items


(Fixed) tow bar; 8 airbags; 4x electrical windows; 4x4; ABS; Airconditioning auto.; Alloy Wheels; Car phone preparation; Central locking; Cruise control; Driver's seat elec.; Driver's seat with memory; El. fold-away mirrors; ESP (el. stability progr.); Fog lights; Front armrest; Handsfree car kit; Leather interior; Leather steering wheel; Multifunction steering wheel; Navigation system; On-board computer; Park sensor; Power steering; Rain sensor; Sliding roof el.; Sun roof; Traction control system; Xenon headlights;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

Brake efficiency tested during road test.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	275/35R22	104Y	CONTINENTAL	PREMIUMCONTA	V	1124	3 mm
Front Right	275/35R22	104Y	CONTINENTAL	PREMIUMCONTA	V	1124	5 mm
Rear Left	315/35R22	111Y	CONTINENTAL	315/35R22	V	3924	4 mm
Rear Right	315/35R22	111Y	CONTINENTAL	PREMIUMCONTA	V	4224	5 mm
Spare	T155/80R19	114M	CONTINENTAL	TEMPORARY	V	0000	6 mm

* Tyre Legend: V=Virgin, R=Recap



Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents, scratches and stone chips on some body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Ofentse Morankwane

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



SPAREWHEEL




COOLANT BOTTLE



OILCAP NO DIPSTICK




CAHSSIS 2




TEST SHEET



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ADDITIONAL 2



ENGINE 1



ENGINE 2



CHASSIS



Control Arm(s) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBACV62090LB14348