



Private Client

DEKRA Boksburg
Bental Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	10/09/2026		316 Bental Ave - 1459
Inspection Date	10/09/2026		DEKRA Boksburg - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS
Manufacturer	ISUZU	Registration Number	JK25JPGP
Model	MU-X 3.0 4X4 DSL AT [2018-2020]	Register Number	YWG653W
VIN	MPAUCS85GJT001012	Date Of First Licensing	
Engine Number		Last COR	10/09/2026
Doors	4	License Expiry Date	
Color	GREY	Power / Displacement	130kw 2999ccm
Year Model	2019	Paint Finish	M - METALLIC
Km Reading	128,255 KM	Fuel	DIESEL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items


(Fixed) tow bar; 8 airbags; 4x electrical windows; 4x4; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; Central locking; Cruise control; Driver's seat elec.; El. fold-away mirrors; ESP (el. stability progr.); Fog lights; Handsfree car kit; Leather interior; Leather steering wheel; Multifunction steering wheel; Navigation system; Park sensor; Power steering; Radio / Cassette; Traction control system;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.7	4.1	-	
Rear	3.7	4.1	-	
Emergency / Parking	2.5	2.7	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/65R18	114T	Continental	Crosscontact	V	2025	5 mm
Front Right	265/65R18	114T	Continental	Crosscontact	V	1825	5 mm
Rear Left	265/65R18	114T	Continental	Crosscontact	V	1825	6 mm
Rear Right	265/65R18	114T	Continental	Crosscontact	V	2025	6 mm
Spare	255/60R18	108S	Bridgestone	Dueler	V	0000	7 mm

* Tyre Legend: V=Virgin, R=Recap



Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Engine mostly covered underneath.

Body • Exterior: Cosmetical enhancements done to some body panels.

Road Test: 4x4 Function not tested.

Options & Accessories

NUDGE BAR, ROOF RACK, SIDE STEPS, CENTRE BRAKE LIGHT, TINTED WINDOWS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Tumelo Molekoa

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



Aircon working



Sparewheel



Coolant bottle



Oil cap and dipstick



Chassis 2



INTERIOR (FRONT DRIVER DOOR)



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD




ENGINE 1



ENGINE 2




CHASSIS




VIN PLATE OR STICKER



LICENSE DISC



ROADWORTHY TEST SHEET



BRAKE TEST REPORT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MPAUCS85GJT001012