




Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	03/08/2026		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	03/08/2026		BOKSBURG - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS CBK MOTORS
Manufacturer	MAZDA	Registration Number	JT03HCGP
Model	BT-50 DBL 2.2 DSL HR SLX D-CAB W/LRD PU [2017-2021]	Register Number	YLF510W
		Date Of First Licensing	
VIN	MM6UR0YD1J0777753	Last COR	03/08/2026
Engine Number	P4AT2522787	License Expiry Date	30/11/2026
Doors	4	Power / Displacement	110kw 2198ccm
Color	BLUE	Paint Finish	M - METALLIC
Year Model	2018	Fuel	DIESEL
Km Reading	172,251 KM	Transmission	MANUAL
Cab / Body Type	DOUBLE CAB		

Vehicle Options & Accessories

Items


(Fixed) tow bar; 6 airbags; 4x electrical windows; ABS; Airconditioning; Alarm system; Central locking; Cruise control; El. mirrors; Fog lights; Handsfree car kit; Multifunction steering wheel; Power steering; Radio cd; Traction control system;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.5	3.0	-	
Rear	2.2	2.4	-	
Emergency / Parking	1.8	2.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/70R16	111S	Bridgestone	Dueler	V	3922	5 mm
Front Right	255/70R16	111S	Bridgestone	Dueler	V	3822	5 mm
Rear Left	255/70R16	111S	Bridgestone	Dueler	V	4622	4 mm
Rear Right	255/70R16	111S	Bridgestone	Dueler	V	4722	4 mm
Spare	255/70R16	111T	Bridgestone	Dueler	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Inspection conditions for the vehicle inspection were sufficient



Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Engine partly covered underneath.
Body • Exterior: Minor dents, scratches and stone chips on some body panels. Cosmetical enhancements done to some body panels.

Options & Accessories

SIDESTEPS, CANOPY

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE


Technician

Tumelo Molekoa


This document was created electronically and is valid without signature.

General Remarks:


The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




Brake test report




Roadworthy test sheet




FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD




RF TYRE TREAD



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Chassis 2



Oil cap and dipstick



coolant bottle



Aircon working

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MM6UR0YD1J0777753