



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	31/08/2026		316 Bental Ave - 1459
Inspection Date	31/08/2026		DEKRA Boksburg - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS
Manufacturer	BMW	Registration Number	JF52TNGP
Model	X3	Register Number	BCG004X
VIN	WBATX16000NV08636	Date Of First Licensing	
Engine Number	55115651	Last COR	2026/08/31
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	110Kw/1995Cc
Year Model	2019	Paint Finish	C - COMMON
Km Reading	130,186 KM	Fuel	DIESEL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items


8 airbags; 4x electrical windows; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; Central locking; Cruise control; El. mirrors; ESP (el. stability progr.); Fog lights; Front armrest; Handsfree car kit; Leather interior; Leather steering wheel; Multifunction steering wheel; Navigation system; On-board computer; Park sensor; Power steering; Radio cd; Sliding roof el.; Sun roof; Traction control system; Xenon headlights;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.4	2.6	-	
Rear	3.0	2.7	-	
Emergency / Parking	2	1.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/45R20	103W	Bridgestone	Alenza	V	0824	4 mm
Front Right	245/45R20	103W	Bridgestone	Alenza	V	1024	4 mm
Rear Left	275/40ZR20	102W	Ilank	L-zeal 56	V	2226	6 mm
Rear Right	275/40ZR20	102W	Ilank	L-ZEAL56	V	2226	6 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient



Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents stone chips and or scratches on various body panels, Cosmetical spray work on various body panels.

Undercarriage: Undercarriage mostly covered limited visibility.

Options & Accessories

TINTED WINDOWS, CENTRE BRAKE LIGHT, ROOF RAILS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Bianca Gleave

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT




90 DEGREE REAR



90 DEGREE LEFT



90 DEGREE RIGHT



ODOMETER




DASHBOARD (W/ ENGINE RUNNING)




INTERIOR (FRONT DRIVER DOOR)



RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



LF TYRE TREAD



Covered



Mostly covered



No spare wheel




Expansion Bottle



Oil cap



Ac



Chassis 2



ENGINE 1




VIN PLATE OR STICKER



LICENSE DISC



ROADWORTHY TEST SHEET



BRAKE REPORT

DEKRA Automotive (PTY) Ltd
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WBATX16000NV08636