



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	05/06/2026		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	05/06/2026		BOKSBURG - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS CBK MOTORS
Manufacturer	MERCEDES BENZ	Registration Number	JC82RFGP
Model	X 156	Register Number	BBT955X
VIN	WDC1569432J648525	Date Of First Licensing	
Engine Number		Last COR	2026/06/05
Doors	5	License Expiry Date	
Color	SILVER	Power / Displacement	115Kw/1595Cc
Year Model	2019	Paint Finish	M - METALLIC
Km Reading	39,157 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items


8 airbags; 4x electrical windows; ABS; Airconditioning; Alarm system; Alloy Wheels; Central locking; Cruise control; El. fold-away mirrors; El. mirrors; ESP (el. stability progr.); Fog lights; Front armrest; Handsfree car kit; Leather interior; Leather steering wheel; Multifunction steering wheel; Navigation system; On-board computer; Park sensor; Power steering; Radio cd; Rain sensor; Sliding roof el.; Sun roof; Traction control system; Xenon headlights;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.4	2.6	-	
Rear	2.8	2.2	-	
Emergency / Parking	1.9	1.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	235/45R19	95V	Continental	Contisport	V	1919	4 mm
Front Right	235/45R19	95V	Continental	Contisport	V	1919	4 mm
Rear Left	235/45R19	95V	Continental	Contisport	V	1919	2 mm
Rear Right	235/45R19	95V	Continental	Contisport	V	1919	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient



Comments

General Comments: ACCORDING TO AGE AND MILEAGE OF VEHICLE NORMAL WEAR AND TEAR ON INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents stone chips and or Scratches on various body panels.

Options & Accessories

CENTRE BRAKE LIGHT, TINTED WINDOWS. ROOF SPOILER, ROOF RAILS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Bianca Gleave

This document was created electronically and is valid without signature.


General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Spare wheel




Expansion bottle




Oil cap and dipstick



Chassis 2



Test report



Test report

