



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	08/07/2026		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	08/07/2026		BOKSBURG - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK MOTORS
Manufacturer	TOYOTA	Registration Number	CAA584022
Model	GR YARIS 1.6 RALLY AWD 5-DR [2022-2025]	Register Number	JPL375L
VIN	JTDAF4E320A021259	Date Of First Licensing	
Engine Number	G16E0032418	Last COR	08/07/2026
Doors	2	License Expiry Date	
Color	WHITE	Power / Displacement	198kw1618ccm
Year Model	2023	Paint Finish	C - COMMON
Km Reading	23,396 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

6 airbags; 2x electrical windows; 4x4; ABS; Airconditioning auto.; Alarm system; Alloy Wheels; Central locking; Cruise control; El. fold-away mirrors; ESP (el. stability progr.); Fog lights; Handsfree car kit; Leather interior; Leather steering wheel; Multifunction steering wheel; Park sensor; Power steering; Rain sensor; Traction control system; Xenon headlights;


VEHICLE INSPECTION



Damage

Repair Way

Rim Rear Left Scratched
Rim Rear Right Scratched



Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40ZR18	92Y	Michelin	Pilot Sport	V	4019	5 mm
Front Right	225/40ZR18	92Y	Michelin	Pilot Sport	V	4019	5 mm
Rear Left	225/40ZR18	92Y	Michelin	Pilot Sport	V	4521	3 mm
Rear Right	225/40ZR18	92Y	Michelin	Pilot Sport	V	4621	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Inspection conditions for the vehicle inspection were sufficient



Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents, scratches and stone chips on some body panels. Cosmetic enhancements done to some body panels.

Undercarriage: Non standard exhaust system fitted.

Road Test: 4x4 Function not tested.

Options & Accessories

REARVIEW CAMERA, RADIO USB

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Tumelo Molekoa

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



FRONT RIGHT CORNER



REAR LEFT CORNER




90 DEGREE REAR



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Aircon working



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Oil cap and dipstick



Chassis 2



Coolant bottle



No sparewheel



CHASSIS



ENGINE 1




ENGINE 2



VIN PLATE OR STICKER



LICENSE DISC



ROADWORTHY TEST SHEET



Rim Rear Left



Rim Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDAF4E320A021259