



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	12/08/2025		573 Trichard Road - 1459
Inspection Date	12/08/2025		DEKRA Boksburg - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	CBK
Manufacturer	SUZUKI	Registration Number	DBK659L
Model	JIMNY 1.3 4X4 [2012-2014]	Register Number	TTB169W
VIN	JSAFJB43V00602760	Date Of First Licensing	
Engine Number	M13A2353652	Last COR	12/08/2025
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	62KW/1328CCM
Year Model	2014	Paint Finish	C - COMMON
Km Reading	14,944 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

2 airbags; 2x electrical windows; 4x4; ABS; Airconditioning; Alarm system; Alloy Wheels; Car phone preparation; Central locking; Detachable tow bar; El. mirrors; Fog lights; Handsfree car kit; Power steering;



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.0	2.2	-	
Rear	1.2	1.3	-	
Emergency / Parking	1.4	1.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/65R15	94H	ACHILES	PLATINUM	V	2514	4 mm
Front Right	205/65R15	94H	ACHILES	PLATINUM	V	2414	4 mm
Rear Left	205/65R15	94H	ACHILES	PLATINUM	V	2414	4 mm
Rear Right	205/65R15	94H	ACHILES	PLATINUM	V	2514	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Vehicle Dirty

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ON INTERIOR, EXTERIOR, AND MECHANICAL PARTS. Body • Exterior: Minor dents, scratches and stone chips on some body panels.

Road Test: 4x4 Function not tested.

Options & Accessories

RADIO USB

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Ofentse Morankwane

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




SPAREWHEEL COVERED




EXPANSION BOTTLE



OIL CAP AND DIPSTICK



BRAKE REPORT



TEST SHEET




FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)








ODOMETER



90 DEGREE FRONT




90 DEGREE RIGHT





LICENSE DISC



VIN PLATE OR STICKER



REAR



CHASSIS



ENGINE 2



ENGINE 1