



Private Client

DEKRA Boksburg
Bentel Ave - 1459
BOKSBURG - GT
011 826 4386



Assignment

Client	Private Client	Inspection Location	BOKSBURG DEKRA
Requested Date	29/08/2025		316 BENTELL AVE BOKSBURG - 1459
Inspection Date	29/08/2025		BOKSBURG - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	JOHAN HARDING
Manufacturer	VOLKSWAGEN	Registration Number	HWC950FS
Model	CADDY MAXI P-VAN 2.0 TDI DSL [2017-2020]	Register Number	HFJ666K
VIN	WV1ZZZ2KZJX003321	Date Of First Licensing	
Engine Number	CLC155757	Last COR	29/08/2025
Doors	2	License Expiry Date	30/06/2026
Color	WHITE	Power / Displacement	81Kw/1968Cc
Year Model	2017	Paint Finish	C - COMMON
Km Reading	173,557 KM	Fuel	DIESEL
Cab / Body Type	PANEL VAN	Transmission	MANUAL

Vehicle Options & Accessories

Items


2 airbags; 2 front seat commercial; ABS; Airconditioning; Alarm system; Alloy Wheels; Central locking; Fog lights; Leather steering wheel; On-board computer; Power steering; Radio cd; Sliding door left; Sliding door right; Traction control system;

VEHICLE INSPECTION



Damage

Repair Way



Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.3	3.4	-	
Rear	2.3	2.4	-	
Emergency / Parking	1.5	1.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/70R15 C	104S	Dunlop	Endura	V	0523	4 mm
Front Right	195/70R15 C	106S	Dunlop	Endura	V	0523	4 mm
Rear Left	195/70R15 C	104S	Dunlop	Endura	V	0523	4 mm
Rear Right	195/70R15 C	106S	Dunlop	Endura	V	0523	4 mm
Spare	205/55R16	94H	Bridgestone	Turanza	V	1143	4 mm

* Tyre Legend: V=Virgin, R=Recap



Diagnostic

A vehicle diagnostic has not been conducted.

Inspection Conditions

Vehicle Dirty

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents, stone chips and or scratches on various body panels. Cosmetical spray work on some body panels. Stone chip on windscreen not in view.

Concluding Remarks


THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician


Bianca Gleave

This document was created electronically and is valid without signature.


General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




Brake report



Test sheet




FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)




ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



LF TYRE TREAD



Spare wheel




LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Covered



CHASSIS



Chassis 2



Oil cap and dipstick



Expansion bottle